

HID® FARGO® HDP®5000e

Printer Firmware
Release Notes

PLT-07880, A.2
April 2025



Copyright

© 2025 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated, or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, HDP, and FARGO are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

Contacts

For technical support, please visit: <https://support.hidglobal.com>.

What's new

Date	Description	Revision
April 2025	Release notes for printer firmware 12.8.4.573.	A.2

A complete list of revisions is available in [Revision history](#).

1.1 Scope

This document provides information on HID® FARGO® HDP®5000e version 12.8.4.573. Included are product features, enhancements, and resolved issues since the previous release.

Note: The reference numbers associated with these features, issues, and fixes are from internal HID Global tracking systems.

1.2 New features

- Added support for new film type: Holographic INTM. (FSA-1230)
- Added support for new ribbon types: YMC, YMCCK, K Premium Resin. (FSA-1232, FSA-1237, FSA-1175)
- Added support for multipass. (FSA-1156)
- Added support for resin scramble for YMCK, YMCKK, and K ribbon types. This does not include YMCCK ribbon type. (FSA-1176)

1.3 Resolved issues

- Fixed an issue causing a laminator error 210 when doing dual-sided multipass batch printing. (FSA2-2160)
- Fixed an issue needing a new EE setting for **Holo Film Transfer Release**. (FSA2-2204)

1.4 Known issues

- The F-panel on single transfer is not legible. (FSA3-1585)
- Canceling print jobs - from separate connections - from the spooler results in a job data error. (FSA2-2245)

Revision history

Date	Description	Revision
April 2025	Release notes for printer firmware 12.8.4.573.	A.2
November 2024	Release notes for printer firmware 12.7.2.511.	A.1
September 2024	Release notes for printer firmware 12.6.1.411.	A.0



hidglobal.com

For technical support, please visit: <https://support.hidglobal.com>

© 2025 HID Global Corporation/ASSA ABLOY AB.

All rights reserved.

PLT-07880, Rev. A.2

Part of ASSA ABLOY